



de Montageanleitung
en Mounting instructions
fr Instructions de montage
sv Monteringsinstruktion
nl Montage-aanwijzing
it Istruzioni di montaggio
fi Asennusohje
es Instrucciones de montaje
da Monteringsvejledning
tr Montaj talimatları

Differenzdruckfühler
Differential Pressure Sensors
Sonde de pression différentielle
Differenstryckgivare
Drukverschilopnemer
Sonda di pressione differenziale
Paine-eroanturit
Sondas de diferencia de presión
Trykdifferensføler
Fark Basıncı Sensörleri

QBM2130-1U
QBM2130-30
QBM2130-5




QBM2130-..



1910z12a

DC 8...33 V
DC18...33V
(500 Ω)
4...20 mA




max. 1.5 mm²



1910z13


Zero Reset

1.




1910z15

2.




1910z14


3.



1910z16



DIP Switch



QBM2130-1U

100 Pa

+/- 100 Pa

+/- 50 Pa

QBM2130-5

500 Pa

250 Pa

200 Pa

QBM2130-30

0...3000 Pa

0...1500 Pa

0...1000 Pa



For additional
information
please refer to
the following
documents on
the Internet:



<http://siemens.com/bt/download>

→ search for " QBM2130"