



**NKPP48HDY**




**NKPPA48HDY**

NOTE: NKP5E88M\*\*, NK688M\*\*, and NK6X88M\*\* are NOT recommended.


#### Module Installation




#### Module Removal



**All cables should flow directly into vertical cable managers on the corresponding side of the Angled Panel.**



Recommended cable routing for terminated modules.



Recommended cable routing for patch cords.

For Instructions in Local Languages  
and Technical Support:

[www.panduit.com/resources/install\\_maintain.asp](http://www.panduit.com/resources/install_maintain.asp)

**PANDUIT**

[www.panduit.com](http://www.panduit.com)

E-mail:  
[techsupport@panduit.com](mailto:techsupport@panduit.com)

Phone:  
866-405-6654