



SLO320

Installation

Outdoor light transmitter
Utomhusgivare för mätning av belysning
Außenhelligkeitsfühler
Sonde de lumière (extérieur)
Sensor de claridad externa
Sensore esterno di luminosità

Instruction
Montageanvisning
Bedienungsanleitung
Instructions d'installation
Instrucciones de empleo
Istruzioni per installazioni

Schneider
Electric



5.
Attention! Unscrew terminal block before connecting wires.


OBS! Lossa plintskruven innan du ansluter.

Achtung! Vor dem Anschließen Klemmblock lösen.

Attention! Avant la connexion bornier dissoudre.

Atencion! Antes de conectar suelte el bloque de terminals.

Attenzione! Prima di conettere avvitare il morsetto.




6.
Don't change Dip-switch 3

NOTICE

INCORRECT VALUES

•Keep **DIP switch 3** in the OFF position, as received from the manufacturer
•If **DIP switch 3** is moved to the ON position, the device will show incorrect values but is not detective.
•**DIP switch 3** must be moved back to the OFF position to operate correctly.

Failure to follow these instructions can result in inaccurate data.



SLO320

Installation

Outdoor light transmitter
Utomhusgivare för mätning av belysning
Außenhelligkeitsfühler
Sonde de lumière (extérieur)
Sensor de claridad externa
Sensore esterno di luminosità

Instruction
Montageanvisning
Bedienungsanleitung
Instructions d'installation
Instrucciones de empleo
Istruzioni per installazioni



部件名称 Part Name	有害物 - Hazardous Substances					
	(Pb)	汞 (Hg)	(Cd)	六价 (Cr (VI))	多溴 苯 (PBB)	多溴二苯醚 (PBDE)
金属部件 Metal parts	O	O	O	O	O	O
塑料部件 Plastic parts	O	O	O	O	O	O
子件 Electronic	X	O	O	O	O	O
触点 Contacts	O	O	O	O	O	O
和 附件 Cables & cabling accessories	O	O	O	O	O	O

本表格依据SJ/T11364的 定 制。
O: 表示 有害物 在 部件所有均 材料中的含量均在GB/T 26572 定的限量要求以下。
X: 表示 有害物 至少在 部件的某一均 材料中的含量超出GB/T 26572 定的限量要求。
(企 可在此处, 根据实 情况对上表中打的技术原因 行 一步 明。)



This table is made according to SJ/T 11364.
O: indicates that the concentration of hazardous substance in all of the homogeneous materials for this part is below the limit as stipulated in GB/T 26572.
X: indicates that concentration of hazardous substance in at least one of the homogeneous materials used for this part is above the limit as stipulated in GB/T 26572