


Illuminated
button
spring-return

Indicator light

	Contacts	Diagram
Device 1	1NO	
Device 2	/	

Connections



Connector	M12 with 8 pole at the bottom	
-----------	----------------------------------	--

