



Connections

Diagram illustrating the connections for the circuit components:

- Terminals 1, 4, 5, 7, 8, 9, 10, 11, and 12 are connected to a common horizontal line.
- Terminals 2, 6, and 12 are connected to a common horizontal line.
- Terminal 3 is connected to a 0V source.
- Terminals 13, 14, 15, and 16 are unconnected.

Connector

M12 with 12 pole
at the bottom



The diagram shows a circular M12 connector with 12 pins numbered 1 through 12. The pins are arranged in two concentric circles. The outer circle contains pins 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12 in clockwise order starting from the top. The inner circle contains pins 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, and 12 in clockwise order starting from the top.

