


## TRIP UNIT LSI



**3**

**Ir =**

**Ir (A)**

100	110	0.95	0.96
90	125	0.94	0.97
80	135	0.93	0.98
70	150	0.92	0.99
63	160	0.91	1.00

**li (x In)**

6	7	8	9
4	5	6	7
3	4	5	6
2	3	4	5
1	2	3	4

**tsd (ms)**

400	400
300	300
200	200
100	100
50	50

**N (%)**

50	100
7.5	10
5.0	12
2.5	14
1.5	16

**tr (s)**

9	10
7.5	12
5.0	14
2.5	16

**tsd (ms)**

400	400
300	300
200	200
100	100
50	50

**Ready**

OFF	ON
-----	----

3P	<input checked="" type="checkbox"/>
4P	<input type="checkbox"/>

	< T max	-	> T max
	< 105% Ir	≥ 105% Ir	> 112% Ir
	< 90% Ir	-	≥ 90% Ir
	OFF		ON

