

Illuminated
button
spring-return

Non-illuminated
button
spring-return

Illuminated
button
spring-return

Emergency
push button


	Contacts	Diagram
Device 1	1NO	
Device 2	1NO	
Device 3	1NO	
Device 4	2NC	

Connections

The diagram shows a breadboard with 12 pins. The connections are as follows:

- Pin 1: Connected to a common ground line.
- Pins 4, 5, and 7: Connected to a common ground line.
- Pins 8, 9, and 10: Connected to a common ground line.
- Pins 2, 6, and 12: Connected to a common ground line.
- Pin 3: Connected to a 0V source.

The diagram also shows a 5V source connected to pins 1, 4, 5, 7, 8, 9, 10, 11, and 12.



Connector	M12 with 12 pole at the bottom	
-----------	--------------------------------	--