















Notice d'utilisation

User manual / Benutzerhandbuch / Manual de usuario /
Handleiding / Manual do usuário / Manuale utente

Gaine MANGE-CABLE

Cable sheath / Kabel-SCHUTZSCHLAUCH / Vaina
MANGE-CABLE / KABELMANTEL / Organizador de
CABOS / Guaina RACCOGLICAVI



∅		 + 			
8mm		100 m	<i>MC08N100M</i>	-	<i>MC08</i>
15mm		50 m	<i>MC15N50M</i>	-	<i>MC15</i>
20mm		30 m	<i>MC20N30M</i>	<i>MC20NPACK2M</i>	<i>MC20</i>
			<i>MC20G30M</i>	<i>MC20GPACK2M</i>	
			<i>MC20A30M</i>	<i>MC20APACK2M</i>	
25mm		20 m	<i>MC25N20M</i>	-	<i>MC25</i>
32mm		15 m	<i>MC32N15M</i>	-	<i>MC32</i>

Mode d'emploi

Instruction for use / Bedienungsanleitung / Instrucciones de uso /
Gebruiksaanwijzing / Instrução de uso / Istruzioni per l'uso

Pour toute manipulation, les câbles doivent être HORS TENSION.

All cables must be POWERED DOWN before handling.


Vor jeder Manipulation müssen die Kabel SPANNUNGSFREI sein.

Para cualquier manipulación, los cables deben estar DESCONECTADOS.

Voor elke handling moeten de kabels UITGESCHAKELD zijn.

Para qualquer manipulação, os cabos devem estar FORA DE TENSÃO.

In caso di manipolazione, i cavi NON devono essere IN TENSIONE.



21 rue Sadi-Carnot 94880 NOISEAU (France)
Tel : (33) 01.45.90.14.14 – Fax : (33) 01.45.90.17.17
contact@cable-equipements.com

www.cable-equipements.com